



enelion

REACH

Declaration of Conformity

Manufacturer/ Producer:

ENELION LTD

52 Miałki Szlak St., Gdańsk 80-717

Product:

Electric Vehicle Charging Station

Model:

Vertica

VM-32-3-X-8-S-04-0-00; VM-32-3-X-8-C-41-0-00; VM-32-3-X-8-C-41-C-00; VM-32-3-X-8-C-41-R-00; VM-32-3-X-8-S-04-C-00;
VM-32-3-X-8-S-04-CR-00; VM-32-3-X-8-S-04-R-00; VM-32-3-X-8-S-04-E-00; VM-32-3-X-8-C-41-B-00; VM-32-3-X-8-C-41-BR-00; VM-32-3-X-8-S-04-B-00;
VM-32-3-X-8-S-04-BR-00; VM-32-3-X-8-C-41-E-00; VM-32-3-X-8-C-41-ER-00; VM-32-3-X-8-S-04-ER-00; VM-32-1-X-8-C-41-O-00; VM-32-1-X-8-S-04-O-00;
VM-32-1-X-8-C-41-RO-00; VM-32-1-X-8-S-04-RO-00; VM-32-1-X-8-C-41-CRO-00; VM-32-1-X-8-S-04-CRO-00; VM-32-1-X-8-C-41-CO-00; VM-32-1-X-8-S-04-
CO-00; VM-32-3-X-8-S-04-0-12; VM-32-3-X-8-S-04-E-12; VM-32-3-X-8-S-04-C-12; VM-32-3-X-8-C-41-0-12; VM-32-3-X-8-C-41-E-12; VM-32-3-X-8-C-41-C-12;
VM-32-3-X-8-S-04-CR-14; VM-32-1-X-8-S-04-CRO-14; VM-32-3-X-8-S-04-R-14; VM-32-1-X-8-S-04-RO-14; VM-32-3-X-8-S-04-B-14; VM-32-3-X-8-S-04-E-14;
VM-32-3-X-8-S-04-E-27; VM-32-3-X-8-S-04-0-27; VM-32-3-X-8-S-04-C-27; VM-32-3-X-8-S-04-0-24; VM-32-3-X-8-S-04-R-24; VM-32-3-X-8-S-04-CR-24;
VM-32-3-X-8-S-04-ER-24; VM-32-3-X-8-S-02-R-24; VM-32-3-X-8-S-02-ER-24; VM-32-3-X-8-S-02-CR-24; VM-32-3-X-8-S-02-0-24; VM-32-1-X-8-S-04-ERO-00;
VM-32-1-X-8-S-04-ENRO-00; VM-32-3-X-8-S-04-ER-27; VM-32-3-X-8-S-04-R-27; VM-32-3-X-8-C-41-CR-32; VM-32-3-X-8-S-04-CR-32; VM-32-1-X-8-C-41-
ERO-00; VM-32-3-X-8-S-04-ER-14; VM-32-3-X-8-S-04-R-32; VM-32-3-X-8-C-41-R-32; VM-32-3-X-8-S-04-ER-32; VM-32-3-X-8-C-41-ER-32; VM-32-1-X-9-S-04-
RO-00; VM-32-1-X-9-S-04-ERO-00; VM-32-3-X-9-S-04-R-00; VM-32-3-X-9-S-04-ER-00; VM-32-1-X-9-S-04-ERO-01; VM-32-1-X-9-S-04-RO-01; VM-32-3-X-9-S-
04-R-01; VM-32-3-X-9-C-41-0-00; VM-32-3-X-9-C-41-0-01; VM-32-3-X-9-S-04-0-00; VM-32-3-X-9-S-04-0-01; VM-32-3-X-9-S-04-ER-01;
VM-32-1-X-8-S-04-BRO-00; VM-32-3-X-8-S-04-ER-37; VM-32-3-X-8-S-04-R-37; VM-32-3-X-9-C-41-R-01; VM-32-3-X-9-C-41-ER-01; VM-32-3-X-8-C-70-ER-00;
VM-32-3-X-8-C-70-R-00; VM-32-3-X-8-C-70-E-00; VM-32-3-X-8-C-70-0-00; VM-32-3-X-8-C-41-ER-14; VM-32-3-X-8-C-41-R-14; VM-32-3-X-9-S-04-CR-00;
VM-32-3-X-9-C-41-R-00; VM-32-1-X-9-S-04-CRO-00; VM-32-1-X-9-S-04-CRO-01; VM-32-1-X-9-S-04-0-00; VM-32-1-X-9-S-04-0-01; VM-32-3-X-9-S-04-0-12;
VM-32-3-X-9-S-04-0-24; VM-32-3-X-9-S-04-C-00; VM-32-3-X-9-S-04-C-01; VM-32-3-X-9-S-04-C-12; VM-32-3-X-9-S-04-CR-01; VM-32-3-X-9-S-04-CR-24;
VM-32-3-X-9-S-04-CR-32; VM-32-3-X-9-S-04-E-00; VM-32-3-X-9-S-04-E-01; VM-32-3-X-9-S-04-ER-14; VM-32-3-X-9-S-04-ER-24; VM-32-3-X-9-S-04-ER-27;
VM-32-3-X-9-S-04-ER-32; VM-32-3-X-9-S-04-ER-37; VM-32-3-X-9-S-04-R-14; VM-32-3-X-9-S-04-R-24; VM-32-3-X-9-S-04-R-27; VM-32-3-X-9-S-04-R-32;
VM-32-3-X-9-S-04-R-37; VM-32-1-X-9-C-41-ERO-00; VM-32-1-X-9-C-41-ERO-01; VM-32-3-X-9-C-41-0-12; VM-32-3-X-9-C-41-C-00; VM-32-3-X-9-C-41-C-01;
VM-32-3-X-9-C-41-C-12; VM-32-3-X-9-C-41-CR-00; VM-32-3-X-9-C-41-CR-01; VM-32-3-X-9-C-41-CR-32; VM-32-3-X-9-C-41-E-00; VM-32-3-X-9-C-41-E-01;
VM-32-3-X-9-C-41-ER-00; VM-32-3-X-9-C-41-ER-32; VM-32-3-X-9-C-41-R-32; VM-32-3-X-9-S-04-ER-40; VM-32-3-X-9-C-70-E-00; VM-32-3-X-9-C-70-0-00;
VM-32-1-X-9-S-04-EO-01; VP-32-3-B-5-X-XX-L-00; VP-32-3-B-5-X-XX-L-00; VP-32-3-B-5-X-XX-2ML-00; VP-32-3-B-5-X-XX-2ML-00; VP-32-3-B-5-X-XX-
2ML2A-00; VP-32-3-S-5-X-XX-2ML2A-00; VP-32-3-B-5-X-XX-2MSL2A-00; VP-32-3-S-5-X-XX-2MSL2A-00; VP-32-3-B-5-X-XX-2ML2D-00; VP-32-3-S-5-X-XX-
2ML2D-00; VP-32-3-B-5-X-XX-2MSL2D-00; VP-32-3-S-5-X-XX-2MSL2D-00; VP-32-3-B-5-X-XX-2MSL-00; VP-32-3-B-5-X-XX-2MSL-00; VP-32-3-B-5-X-XX-
L2A-00; VP-32-3-S-5-X-XX-L2A-00; VP-32-3-B-5-X-XX-SL2A-00; VP-32-3-S-5-X-XX-SL2A-00; VP-32-3-B-5-X-XX-L2D-00; VP-32-3-S-5-X-XX-L2D-00;
VP-32-3-B-5-X-XX-BL-00; VP-32-3-S-5-X-XX-BL-00; VP-32-3-B-5-X-XX-2MBL-00; VP-32-3-S-5-X-XX-2MBL-00; VP-32-3-B-5-X-XX-2MBL2A-00; VP-32-3-S-5-
X-XX-2MBL2A-00; VP-32-3-B-5-X-XX-2MBSL2A-00; VP-32-3-S-5-X-XX-2MBSL2A-00; VP-32-3-B-5-X-XX-2MBL2D-00; VP-32-3-S-5-X-XX-2MBL2D-00;
VP-32-3-B-5-X-XX-2MBSL2D-00; VP-32-3-S-5-X-XX-2MBSL2D-00; VP-32-3-B-5-X-XX-2MBSL-00; VP-32-3-S-5-X-XX-2MBSL-00; VP-32-3-B-5-X-XX-BL2A-00;
VP-32-3-S-5-X-XX-BL2A-00; VP-32-3-B-5-X-XX-BSL2A-00; VP-32-3-S-5-X-XX-BSL2A-00; VP-32-3-B-5-X-XX-BL2D-00; VP-32-3-S-5-X-XX-BL2D-00;
VP-32-3-B-5-X-XX-MBL-00; VP-32-3-S-5-X-XX-MBL-00; VP-32-3-B-5-X-XX-MBLA-00; VP-32-3-S-5-X-XX-MBLA-00; VP-32-3-B-5-X-XX-MBLD-00;
VP-32-3-S-5-X-XX-MBLD-00; VP-32-3-B-5-X-XX-BLA-00; VP-32-3-S-5-X-XX-BLA-00; VP-32-3-B-5-X-XX-BLD-00; VP-32-3-S-5-X-XX-BLD-00; VP-32-3-B-5-X-
XX-BSL-00; VP-32-3-S-5-X-XX-BSL-00; VP-32-3-B-5-X-XX-BSL2D-00; VP-32-3-S-5-X-XX-BSL2D-00; VP-32-3-B-5-X-XX-ML-00; VP-32-3-S-5-X-XX-ML-00;
VP-32-3-B-5-X-XX-MLA-00; VP-32-3-S-5-X-XX-MLA-00; VP-32-3-B-5-X-XX-MLD-00; VP-32-3-S-5-X-XX-MLD-00; VP-32-3-B-5-X-XX-LA-00; VP-32-3-S-5-X-
XX-LA-00; VP-32-3-B-5-X-XX-LD-00; VP-32-3-S-5-X-XX-LD-00; VP-32-3-B-5-X-XX-SL-00; VP-32-3-S-5-X-XX-SL-00; VP-32-3-B-5-X-XX-SL2D-00;
VP-32-3-S-5-X-XX-SL2D-00; VP-32-3-S-5-X-XX-0-00; VP-32-3-B-5-X-XX-0-00; VP-32-3-B-5-X-XX-MBLF-00; VP-32-3-S-5-X-XX-MBLF-00; VP-32-3-B-5-X-XX-
MBLFA-00; VP-32-3-S-5-X-XX-MBLFA-00; VP-32-3-B-5-X-XX-MBLFD-00; VP-32-3-S-5-X-XX-MBLFD-00; VP-32-3-B-5-X-XX-F-00; VP-32-3-B-5-X-XX-LF-00;
VP-32-3-B-5-X-XX-LFA-00; VP-32-3-S-5-X-XX-LF-00; VP-32-3-S-5-X-XX-LFA-00; VP-32-3-S-5-X-XX-BLFA-00; VP-32-3-B-5-X-XX-BLFA-00; VP-32-3-S-5-X-XX-
BLFD-00; VP-32-3-B-5-X-XX-BLFD-00; VP-32-3-S-5-X-XX-BLFD-00; VP-32-3-B-5-X-XX-BLFD-00; VP-32-3-P-5-X-XX-2ML-00; VP-32-3-B-5-X-XX-MLF-00;
VP-32-3-P-5-X-XX-2ML2A-00; VP-32-3-90065-5-X-XX-0-00; VP-32-3-90065-5-X-XX-SL2D-00; VP-32-3-90065-5-X-XX-SL2A-00; VP-32-3-90065-5-X-XX-
SL-00; VP-32-3-90065-5-X-XX-MLD-00; VP-32-3-90065-5-X-XX-MLA-00; VP-32-3-90065-5-X-XX-ML-00; VP-32-3-90065-5-X-XX-MBLD-00; VP-32-3-
90065-5-X-XX-MBLA-00; VP-32-3-90065-5-X-XX-MBL-00; VP-32-3-90065-5-X-XX-LFA-00; VP-32-3-90065-5-X-XX-LF-00; VP-32-3-90065-5-X-XX-LD-00;
VP-32-3-90065-5-X-XX-LA-00; VP-32-3-90065-5-X-XX-L2D-00; VP-32-3-90065-5-X-XX-L2A-00; VP-32-3-90065-5-X-XX-L-00; VP-32-3-90065-5-X-XX-
BSL2D-00; VP-32-3-90065-5-X-XX-BSL2A-00; VP-32-3-90065-5-X-XX-BSL-00; VP-32-3-90065-5-X-XX-BLFD-00; VP-32-3-90065-5-X-XX-BLFD-00;
VP-32-3-90065-5-X-XX-BLA-00; VP-32-3-90065-5-X-XX-BL2D-00; VP-32-3-90065-5-X-XX-BL2A-00; VP-32-3-90065-5-X-XX-BL-00; VP-32-3-90065-5-X-XX-
2MSL2D-00; VP-32-3-90065-5-X-XX-2MSL2A-00; VP-32-3-90065-5-X-XX-2MBL-00; VP-32-3-90065-5-X-XX-2MBL2A-00; VP-32-3-90065-5-X-XX-
2MBL2D-00; VP-32-3-90065-5-X-XX-MBLFD-00; VP-32-3-90065-5-X-XX-MBLFA-00; VP-32-3-90065-5-X-XX-MBLF-00; VP-32-3-90065-5-X-XX-BLFA-00;
VP-32-3-90065-5-X-XX-BLD-00; VP-32-3-90065-5-X-XX-2MSL-00; VP-32-3-90065-5-X-XX-2ML2A-00; VP-32-3-90065-5-X-XX-2ML-00; VP-32-3-90065-5-X-
XX-2MBSL2D-00; VP-32-3-90065-5-X-XX-2MBSL2A-00; VP-32-3-90065-5-X-XX-2MBSL-00; VP-32-3-90055-5-X-XX-0-00; VP-32-3-90055-5-X-XX-2MB-
L2A-00; VP-32-3-90055-5-X-XX-2MBL2D-00; VP-32-3-90055-5-X-XX-2MBSL2A-00; VP-32-3-90055-5-X-XX-2MBSL2D-00; VP-32-3-90055-5-X-XX-2ML-00;



enelion

VP-32-3-9005S-5-X-XX-2ML2A-00; VP-32-3-9005S-5-X-XX-2ML2D-00; VP-32-3-9005S-5-X-XX-2MSL-00; VP-32-3-9005S-5-X-XX-2MSL2A-00; VP-32-3-9005S-5-X-XX-2MSL2D-00; VP-32-3-9005S-5-X-XX-BL-00; VP-32-3-9005S-5-X-XX-BL2A-00; VP-32-3-9005S-5-X-XX-BL2D-00; VP-32-3-9005S-5-X-XX-L-00; VP-32-3-9005S-5-X-XX-L2A-00; VP-32-3-9005S-5-X-XX-L2D-00; VP-32-3-9005S-5-X-XX-MLA-00; VP-32-3-9005S-5-X-XX-SL-00; VP-32-3-9005S-5-X-XX-SL2A-00; VP-32-3-6005M-5-X-XX-2ML-00; VP-32-3-6005M-5-X-XX-L-00; VP-32-3-B-6-X-XX-L-00; VP-32-3-S-6-X-XX-L-00; VP-32-3-S-6-X-XX-2MSL2A-00; VP-32-3-6005M-5-X-XX-2MPL2A-00; VP-32-3-S-5-X-XX-L-37; VP-32-3-B-5-X-XX-L-37; VP-32-3-9005S-5-X-XX-L-37; VP-32-3-S-5-X-XX-2MPL2D-00; VP-32-3-B-5-X-XX-2MPL2D-00; VP-32-3-9005S-6-X-XX-2MSL2A-00; VP-32-3-S-6-X-XX-MLFA-00; VP-32-3-S-6-X-XX-0-00; VP-32-3-S-6-X-XX-2MBSL2A-00; VP-32-3-S-6-X-XX-2ML2A-00; VP-32-3-B-6-X-XX-2MBSL2A-00; VP-32-3-B-6-X-XX-2MBSL2D-00; VP-32-3-B-6-X-XX-2ML-00; VP-32-3-B-6-X-XX-2ML2A-00; VP-32-3-B-6-X-XX-2ML2D-00; VP-32-3-B-6-X-XX-2MPL2D-00; VP-32-3-B-6-X-XX-2MSL2A-00; VP-32-3-B-6-X-XX-2MSL2D-00; VP-32-3-B-6-X-XX-BL-00; VP-32-3-B-6-X-XX-BL2A-00; VP-32-3-B-6-X-XX-BL2D-00; VP-32-3-B-6-X-XX-0-00; VP-32-3-B-6-X-XX-L-37; VP-32-3-B-6-X-XX-L2A-00; VP-32-3-B-6-X-XX-L2D-00; VP-32-3-B-6-X-XX-LFA-00; VP-32-3-B-6-X-XX-SL-00; VP-32-3-B-6-X-XX-SL2A-00; VP-32-3-B-6-X-XX-SL2D-00; VP-32-3-9005S-6-X-XX-SL2A-00; VP-32-3-S-6-X-XX-2MBSL2D-00; VP-32-3-S-6-X-XX-2MBSL2D-00; VP-32-3-S-6-X-XX-2ML-00; VP-32-3-S-6-X-XX-2ML2D-00; VP-32-3-S-6-X-XX-2MSL-00; VP-32-3-S-6-X-XX-2MSL2D-00; VP-32-3-S-6-X-XX-BL-00; VP-32-3-S-6-X-XX-BL2A-00; VP-32-3-S-6-X-XX-SL2D-00; VP-32-3-S-6-X-XX-SL2A-00; VP-32-3-S-6-X-XX-SL-00; VP-32-3-S-6-X-XX-LFA-00; VP-32-3-S-6-X-XX-LF-00; VP-32-3-S-6-X-XX-L2D-00; VP-32-3-S-6-X-XX-L2A-00; VP-32-3-S-6-X-XX-BSL2D-00; VP-32-3-S-6-X-XX-BSL2A-00; VP-32-3-S-6-X-XX-BSL-00; VP-32-3-S-6-X-XX-BLFD-00; VP-32-3-S-6-X-XX-BLF-00; VP-32-3-6005M-6-X-XX-2MPL2A-00; VP-32-3-9006S-6-X-XX-0-00; VP-32-3-9006S-6-X-XX-2MBSL-00; VP-32-3-9006S-6-X-XX-2MBSL2D-00; VP-32-3-9006S-6-X-XX-2MBSL2A-00; VP-32-3-9006S-6-X-XX-2MBSL2D-00; VP-32-3-9006S-6-X-XX-2ML-00; VP-32-3-9006S-6-X-XX-2ML2A-00; VP-32-3-9006S-6-X-XX-2ML2D-00; VP-32-3-9006S-6-X-XX-2MSL-00; VP-32-3-9006S-6-X-XX-2MSL2A-00; VP-32-3-9006S-6-X-XX-2MSL2D-00; VP-32-3-9006S-6-X-XX-BL-00; VP-32-3-9006S-6-X-XX-BL2A-00; VP-32-3-9006S-6-X-XX-BL2D-00; VP-32-3-9006S-6-X-XX-BLF-00; VP-32-3-9006S-6-X-XX-BLFD-00; VP-32-3-9006S-6-X-XX-BLF-00; VP-32-3-9006S-6-X-XX-L-00; VP-32-3-9006S-6-X-XX-L2A-00; VP-32-3-9006S-6-X-XX-L2D-00; VP-32-3-9006S-6-X-XX-LF-00; VP-32-3-9006S-6-X-XX-LFA-00; VP-32-3-9006S-6-X-XX-MLFA-00; VP-32-3-9006S-6-X-XX-SL-00; VP-32-3-9006S-6-X-XX-SL2A-00; VP-32-3-9006S-6-X-XX-SL2D-00; VP-32-3-9006S-6-X-XX-BSL2D-00; VP-32-3-9005S-6-X-XX-0-00; VP-32-3-9005S-6-X-XX-2MBSL2A-00; VP-32-3-9005S-6-X-XX-2MBSL2D-00; VP-32-3-9005S-6-X-XX-2ML2A-00; VP-32-3-9005S-6-X-XX-2ML2D-00; VP-32-3-9005S-6-X-XX-2MPL2D-00; VP-32-3-9005S-6-X-XX-2MSL2D-00; VP-32-3-9005S-6-X-XX-BL-00; VP-32-3-9005S-6-X-XX-BL2A-00; VP-32-3-9005S-6-X-XX-BL2D-00; VP-32-3-9005S-6-X-XX-L-00; VP-32-3-9005S-6-X-XX-L-37; VP-32-3-9005S-6-X-XX-L2A-00; VP-32-3-9005S-6-X-XX-L2D-00; VP-32-3-9005S-6-X-XX-SL-00; VP-32-3-9005S-6-X-XX-SL2D-00; VP-32-3-9005S-6-X-XX-LF-00; VP-32-3-B-6-X-XX-LA-00; VP-32-3-B-6-X-XX-MLA-00; VP-32-3-S-6-X-XX-MLA-00; VP-32-3-S-6-X-XX-ML-00; VP-32-3-9006S-6-X-XX-MLA-00; VP-32-3-9005S-6-X-XX-LA-00; VP-32-3-9005S-6-X-XX-MLA-00; VP-32-3-S-6-X-XX-MLF-00; VP-32-3-S-5-X-XX-MLF-00; VP-32-3-B-6-X-XX-2MSL-00; VP-32-3-B-6-X-XX-L-00; VP-32-1-B-6-X-XX-2MSL2A-00; VP-32-1-S-6-X-XX-2MSL2A-00; VP-32-1-S-6-X-XX-MLFA-00; VP-32-1-B-6-X-XX-MLFA-00; VP-32-3-B-6-X-XX-2MBSL-00; VP-32-3-9005S-6-X-XX-2MBSL-00; VP-32-3-B-6-X-XX-L2D-00; VP-32-3-S-6-X-XX-2MBSL-00; VP-32-3-B-6-X-XX-2MBSL-00; VP-32-3-9005S-5-X-XX-2MBSL-00; VP-32-3-B-6-X-XX-2ML2DDH-00; VP-32-3-9006S-6-X-XX-MLF-00; VP-32-3-PCAS-6-X-XX-2MSL-00; VP-32-3-PCAS-6-X-XX-MLF-00; VP-32-3-B-6-X-XX-2MPL2A-00; VP-32-3-B-6-X-XX-PL2A-00; VP-32-3-S-4-X-XX-0-00

We declare that above products meet the following European directives:

Low Voltage Directive (LVD) 2014/35/EU
Electromagnetic Compatibility (EMC) Directive 2014/30/EU
Radio Equipment Directive (RED) 2014/53/EU
Restriction of Hazardous Substances (RoHS) 2011/65/EU & 2015/863

The following harmonised standards have been applied:

PN-EN EN 300 328 V2.2:2020-03; PN-EN 62196-2:2017-06;
PN-EN IEC 61851-1:2019-10; PN-EN IEC 61851-21-2:2021-09; PN-EN 62196-1:2015-05;
PN-EN EN 301 511 V12.5.1:2017-10; PN-EN EN 300 330 V2.1.1:2017-08;
PN-EN EN 301 489-1 V2.2.3:2020-07; PN-EN EN 301 489-17 V3.2.4:2021-05

Place and date of issue
Gdańsk, 28 WRZEŚNIA 2023

Name, function, signature
DARIUSZ KOBIELA
MEMBER OF THE BOARD

Dariusz Kobiela

Name, function, signature
BARTŁOMIEJ GAST
MEMBER OF THE BOARD

Bartłomiej Gast